HOTELS AND MOTELS



MOST CITED STANDARDS FOR HOTELS AND MOTELS JANUARY 1, 2001 TO DECEMBER 31, 2001

RANK		STANDARDS CITED	NUMBER			
1	1910.134	Respiratory protection was not provided for employees in the workplace.	22			
2	80-5	This section applies to abrasive wheel machinery requirements and guarding.	13			
3	1910.157	The requirements of this section apply to the placement, use, maintenance, and testing of portable fire extinguishers provided for the employees' use.	12			
4	1910.305(b)	Conductors entering boxes, cabinets, or fittings were not protected from abrasion, and openings through which conductors entered were not effectively closed . All pull boxes, junction boxes, and fittings were not provided with covers approved for the purpose.	11			
5	1910.147	The minimum performance requirements for the control of hazardous energy were not met for the servicing and maintenance of machines and equipment.	10			
6	80-4	Requirements for woodworking machinery were not met.	9			
6	1910.1200(e)	Employers did not develop and implement a written hazard communication program for their work places.	9			
7	1910.304(f)	The path to ground from circuits, equipment, and enclosures was not permanent and continuous. Included were missing ground pins and broken ground wires.	8			
8	60-2	Safe work places and practices were not provided. Standards for an Occupational Safety and Health Program were not met.	7			
	(Page 1 of 2)					

Source: IMIS, Citations from HIOSHL-2. Total cited was 200.

HOTELS AND MOTELS

RANK		STANDARDS CITED	NUMBER
9	1910.132	Personal safety equipment or clothing was not worn by employees who were exposed to hazards where these devices were expected to prevent injury. Employers did not assess the workplace for hazards and provide training.	6
9	1910.303(g)	Sufficient access and working space was not provided and maintained about all electrical equipment to permit ready and safe operation and maintenance of such equipment. In locations where electrical equipment was exposed to physical damage, enclosures or guards were not so arranged and of such strength as to prevent such damage.	6
9	1910.305(g)	Flexible cords were used as a substitute for fixed wiring where not permitted. Flexible cords were not connected to devices and fittings so that strain relief was provided, which would have prevented pull from being transmitted to joints.	6
		(Page 2 of 2)	

Source: IMIS, Citations from HIOSHL-2. Total cited was 200.